

090607Z JUL 80

5 A method of manufacturing a micromachined component includes using a first liquid to etch a first layer (140) located underneath a second layer (150), exposing the second layer to a second liquid that is inorganic and miscible in carbon dioxide, and supercritical drying the micromachined component with carbon dioxide.

10